

RAZOR TIG 200ACDC PULSE



To CALIBRATE THE REMOTE CONTROL TORCH OR FOOT CONTROL

1. Push both keys on display board at the same time and switch on the main power switch; keep holding the keys for 5 seconds, and release it after three beeps.
2. Code P01 displayed. Push the function key (the left button) to choose the code P11, then push the 2T4T button (the right button) display will show " _ _ _", adjust the torch or foot pedal to minimum setting and press 2T4T button, the display will show " _ _ _", adjust the torch or foot control to maximum and press the 2T4T button display will show "OK"
3. Switch off and restart machine.